

Case History	Abnormal Vibration of Gear Reducer	General machine
Forced		

Object Machine	Gear reducer for motor driven fan
Observed Phenomena	A monitoring accelerometer mounted on the gear reducer indicated an alarm level vibration value.
Cause Presumed	It was estimated that the problem was specific to this gear (tooth contact, pitch error, tooth damage, etc.) as the models of the same type experienced no such problem.
Analysis and Data Processing	<p>Time history analysis, frequency analysis and envelope analysis of the measured vibration data were performed as follows:</p> <ul style="list-style-type: none"> ▪ Time history analysis—Striking phenomenon → Separation of tooth surface ▪ Frequency analysis—Major component being due to tooth meshing on the second stage → Second stage gear ▪ Envelope analysis—Rotational component of gear intermediate shaft → Second stage gear on the intermediate shaft side <p>In addition, a hammering test confirmed no resonance.</p> <p>Then, as a result of observation of the tooth surface, a slight indentation was detected.</p>
Countermeasures and Results	<p>After replacing the gear intermediate shaft, adjustment was made of the input gear contact, and thus vibration ceased.</p> <p>Checking by the gear manufacture of the gear on the intermediate shaft side second stage proved that the pitch error was more than the reference value.</p>
Lesson Learned	Analysis based on the basics may clarify the defects identified to significant degree.
References	Nothing in particular
Keyword	Pitch error, envelope analysis, AM modulation




Fig.1: Arrangement of gear reducer




Fig.3: Frequency analysis of acceleration (Hz)




Fig.2: Time history analysis




Fig.4: Result of frequency & modulation analysis